

Products and Bill send to:

NXT TECHNICAL TEAM

2830 Mount Niguel Circle

Corona, CA 92882

O. 817-723-4154

Email: nxt.technicalteam@nxt-team.com

www.ntx-team.com

- Guarantee to have your products shipped back in 1 or 2 business days.
- Have 90 days guarantee on Our Repairs.
- Have RUSH Repair Service
- *Customer pay for shipping charge*

<u>MODEL:</u>	<u>ASSEMBLY:</u>	<u>REPAIR COST:</u> <i>(Flat Rate + Shipping)</i>
7400/7700-DCU	280450	\$ 500.00
7441/7740-DCU	330025	\$ 500.00
7460/7760-UCI	330085	\$ 310.00
7801/7802/ 780X-TAP	330195	\$ 225.00
7804/7806/7850-DIAL TAP	330670	\$ 310.00
7410-HHC	280640	\$ 300.00
72XX-UCs <i>Unitary Control</i>	330345	\$ 175.00
7790A/7791/7793	330605	\$ 225.00
*7798/B/C	330760	\$ 200.00
* <i>If Display 7798/B needs to replace ... will add another \$175.00</i>		
* <i>If Key-Pad 7798/B needs to replace ... will add another \$175.00</i>		
*7728 I/SITE	330720	\$ 300.00
* <i>If Display 7728 needs to replace ... will add another \$175.00</i>		
* <i>If Key-Pad 7728 needs to replace ... will add another \$175.00</i>		
LCD Display 7728/7798/B (send by itself).	330720/330915	\$150.00
7780 <i>Lighting Control</i>	30555	\$ 250.00
7756 PCU	30790	\$ 350.00
7718 PCU	30435	\$ 250.00
7716 PCU	30375	\$ 250.00
7920-PDU <i>Access Control</i>	30515	\$ 200.00
7910A-DPU	30325	\$ 200.00
7930	30296	\$ 175.00
7940	30296	\$ 175.00
CLX and RS232 Cards	30380-01 or -02	\$ 100.00
*MRs <i>Micro Regulator Control</i>		\$ 160.00
* <i>If needs to replace "Whole Damper" ... will add another \$75.00</i>		
* <i>If needs to replace "Sensor" ... will add another \$25.00</i>		
All Expansion Cards of 7400/7700		\$ 100.00
All Expansion Cards of 7716 or 7718		\$ 100.00
*MIP Card		\$ 100.00
* <i>If Socket needs to replace....will add another \$30.00</i>		
20010 – *NPR	330895	\$ 300.00
* <i>If needs to replace Power Supply (External) ... will add another \$75.00</i>		

Note: Any Program/BOOT Chip needs to Upgrade ... will add another \$35.00